

Owner Manual

Parts List


Part #	Description	Quantity	Part #	Description	Quantity
A	Heron Body	2	X1	Flat Head Screw	8
B	Right Leg	2	X2	Long Screw	4
C	Left Leg	2	X3	Hex Head Screw	6
D	Base	1	X4	Round Head Screw	1
E	Birdbath Bowl	1	Y1	Washer	10
F	Bird	1	Y2	Lock Washer	6
G	Mounting Bracket	1	Y3	Nut	4

Friendly Reminders

- * During assembly, place the empty carton beneath the casting parts to protect the finish from damage
- * Do not over-tighten! Aluminum is a soft metal, insert screws carefully and don't over-tighten.
- * HOUSEHOLD TOOLS REQUIRED:
Adjustable wrench and Philips screwdriver


Step 1: Assemble Heron Body and Legs

Lay heron body on the ground, starting with one Heron body. Place left leg and screw onto the heron's "thigh" by using 2 flat head screws (X1). Proceed to next leg. Follow same instructions for the second bird. Tighten all screws.




Step 2: Heron Body, Base and Mounting Bracket

Pick any of sub-assembled Heron. Matching its legs to the feet mounting holes of Base D, attach Heron to the base with screws (X2), washers (Y1), and nuts (Y3). Don't tighten the screws yet. Using the same procedure, assemble another Heron to the base. Matching the mounting holes of mounting bracket G to the mounting holes of both Heron neck, attach mounting bracket to heron neck by using screws (X3), lock washers (Y2), and washers (Y1).



Step 3: Bowl and Mounting Bracket

Turn bowl upside down and place it on the ground. Attach mounting bracket to the bowl by using screws (X3), lock washers (Y2), and washers (Y1). Turn upright and attach bird F to the bowl with screw (X4).



Special Notes

This birdbath is made with an old world, traditional hand-crafted look. Because of the nature of cast iron or aluminum, you may find roughness on the surface of the design. Slight pinholes are also present in the metal casting that is customary to hand-crafted original iron work. These irregularities enhance the individuality of the piece. They should not be considered defects.

Care and Maintenance

1. Should the finish get scratched down to the metal surface, cover the scratched area with enamel paint as soon as possible to prevent rust.
2. Cleaning - Use mild soap and water. Do not use harsh abrasive material, cleansers or bleach products. Rinse with clean water and dry thoroughly with rags or direct sunlight.
3. Periodically check and tighten all bolts.