
















3 X 6 M



①	 $\phi 38 \times 1930$	X9
②	 $\phi 38 \times 1585$	X8
③	 $\phi 38 \times 1930$	X8
A		X6
B		X6
C		X8
D	 M6*50mm	X8

1

Ⓔ		X70
Ⓕ		X8
Ⓖ	 $\phi 5$	X24
Ⓕ		X1
Ⓖ		X2
Ⓖ		X2

2

1



① 9pcs




A 6pcs






B 6pcs





2



② 8pcs




3



4



3



H 1pc




E 46pcs







5

4




3 4pcs



6

5



③ 4pcs





6





Ⓒ 8pcs




Ⓓ 8pcs






7



8





7











(E) 16pcs (I) 2pcs (J) 2pcs

8

(G) 24pcs (F) 8pcs






9

10

9

10



11

12