







ASSEMBLY INSTRUCTION


















ASSEMBLY INSTRUCTION



ASSEMBLY INSTRUCTION


A KM6x40mm  X120	B M5x9mm  X120	C M6x50mm  X40	D M3.5x14mm  X40
E  X8	F  X1	G  X1	H  X1

ASSEMBLY INSTRUCTION

①  X1	②  X1	③  X1
④  X2	⑤  X2	⑥  X1
⑦  X1	⑧  X2	⑨  X4
⑩  X1	⑪  X4	⑫  X4
⑬  X2	⑭  X1	⑮  X1


ASSEMBLY INSTRUCTION

16




X1

17




X1

18




X1

19




X1

20




X2

21




X2

22




X4

23




X4

ASSEMBLY INSTRUCTION



ASSEMBLY INSTRUCTION

STEP 1





X2

A KM6*40



*4

STEP 2




A KM6*40




*16

ASSEMBLY INSTRUCTION

STEP 3




STEP 4




ASSEMBLY INSTRUCTION

STEP 5




STEP 6



ASSEMBLY INSTRUCTION

STEP 7




B M15*9



*4

STEP 8




A KM6*40



*8

ASSEMBLY INSTRUCTION

STEP 9




A KM6*40



*2

STEP 10




A KM6*40




*2

ASSEMBLY INSTRUCTION

STEP 11




STEP 12




ASSEMBLY INSTRUCTION

STEP 13




STEP 14



ASSEMBLY INSTRUCTION


STEP 15



B	M15*9	C	6*50mm
	*2		*2


ASSEMBLY INSTRUCTION

STEP 16



ASSEMBLY INSTRUCTION

STEP 17




[B] M15*9



*4


ASSEMBLY INSTRUCTION

STEP 18




ASSEMBLY INSTRUCTION

STEP 19




ASSEMBLY INSTRUCTION

STEP 20





STEP 21




ASSEMBLY INSTRUCTION

STEP 22




D M3. 5*14mm	F
	
*4	*1

ASSEMBLY INSTRUCTION



ASSEMBLY INSTRUCTION

STEP 1





X2

A KM6*40



*4

STEP 2




A KM6*40



*16

ASSEMBLY INSTRUCTION


STEP 3



X2

B M15*9	C 6*50mm
 *4	 *2


STEP 4




B M15*9
 *8

ASSEMBLY INSTRUCTION

STEP 5




STEP 6



ASSEMBLY INSTRUCTION

STEP 7




B M15*9



*4

STEP 8




A KM6*40



*8

ASSEMBLY INSTRUCTION

STEP 9




A KM6*40



*2

STEP 10





A KM6*40





*2

ASSEMBLY INSTRUCTION

STEP 11




STEP 12



Note: Screw on both sides


ASSEMBLY INSTRUCTION

STEP 13



6*50mm	C	M15*9	B
*2		*2	


STEP 14



M15*9	B
*4	

ASSEMBLY INSTRUCTION


STEP 15



M15*9	B	6*50mm	C
*2		*2	


ASSEMBLY INSTRUCTION

STEP 16



ASSEMBLY INSTRUCTION

STEP 17




[B] M15*9



*4


ASSEMBLY INSTRUCTION

STEP 18




ASSEMBLY INSTRUCTION

STEP 19




ASSEMBLY INSTRUCTION

STEP 20








STEP 21

STEP 14



ASSEMBLY INSTRUCTION

STEP 22



D M3.5*14mm




*4

G




*1

ASSEMBLY INSTRUCTION



ASSEMBLY INSTRUCTION

STEP 1




A KM6*40



*8

STEP 2




A KM6*40



*4

ASSEMBLY INSTRUCTION

STEP 3




A KM6*40



*2

STEP 4




A KM6*40



*2


ASSEMBLY INSTRUCTION

STEP 5



M15*9	B	6*50mm	C
	*4		*4


STEP 6



M15*9	B
	*4

ASSEMBLY INSTRUCTION

STEP 7




M15*9	B	6*50mm	C
			
	*4		*4


[illegible]

ASSEMBLY INSTRUCTION

STEP 9




STEP 10



ASSEMBLY INSTRUCTION

STEP 11



D M3. 5*14mm

*4