


# ASSEMBLY INSTRUCTION

A




M6x16

B



x4  $\phi 6 \times \phi 18$


C



x4 M5

x1

## STEP 1



## STEP 2

