











READ AND SAVE THIS INSTRUCTION FOR FUTURE USE


ASSEMBLY INSTRUCTION



									
A	2pcs	B	4pcs	C	7pcs	D	22pcs	E	28pcs
									
F	28pcs	G	1pc	H	1pc	I	1pc	J	1 pc
									
K	1pc	L	1pc	M	2pcs	N	1pc	O	4pcs
									
P	1pc	Q	2pcs	R	2pcs	S	10pcs	T	14pcs
									
U	8pcs								



F x12

01





A x1
B x2
K x1
L x1
M x2
S x1

02




D x8
E x12
F x6

03




04

G x1
I x1
S x4





05

C x2
D x2
F x6




06


D x2
E x2




D x6
E x6




Dx4
Ex4



T x14



R x2
U x8



11

S

11

H

S

12

J

S

13

12

C

11

C

14

12

11

10

B

F

F

F

F

A

12

11

10

E

E

C x4 A x1
H x1 B x2
J x1 E x4
S x4 F x4



Ox4

12

This diagram illustrates the final step of the assembly process. It shows a three-dimensional view of the assembled cabinet, which includes a top panel, a middle drawer, and a bottom door. A separate rectangular panel, labeled with the number 16 inside a circle, is shown below the cabinet. A curved arrow points from this panel to the bottom edge of the cabinet's main body, indicating that it should be attached to the underside. A straight arrow points to the drawer, indicating it should be pushed back into its slot. Small circles and lines near the drawer's base represent the internal hardware and the attachment point for the bottom panel.

12

C x1
N x1
Q x2
S x1



P x1

