






Installation & Assembly

Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other






For easier and better assembly,
2 or more adults are required.

A		S4	1PC	H		M8	8PCS
B		M8*55	4PCS	I		Ø8	8PCS
C		M8*40	8PCS	J		Ø6	10PCS
D		M6*45	10PCS	K		S10, S13	1PC
E		M6*10	18PCS	L			1PC
F		M5*25	8PCS				
G		Ø3*12	2PCS				


Step1

D		M6*45	4PCS
J		Ø6	4PCS
A		S4	




Step2

G		Ø3*12	2PCS
L			





Step3

D		M6*45	4PCS
J		Ø6	4PCS
A		S4	



Don't tighten the screw completely, just tighten it 80%




For easier and better assembly, 2 or more adults are required.



Step4

D		M6*45	2PCS
J		Ø6	2PCS
A		S4	

Don't tighten the screw completely, just tighten it 80%



The welding bead is on the side




For easier and better assembly, 2 or more adults are required.

Step5


E		M6*10	6PCS
A		S4	

All screws are fully tightened




Step6


B		M8*55	2PCS
H		M8	2PCS
A		S4	
K		S10, S13	



Step7			
B		M8*55	2PCS
H		M8	2PCS
A		S4	
K		S10, S13	




Step8			
C		M8*40	8PCS
I		Ø8	8PCS
H		M8	4PCS
A		S4	
K		S10, S13	




Step9

F		M5*25	8PCS
A		S4	





Step10



Step11


X2



Step12

X2



E		M6*10	8PCS
A		S4	



Step13

E		M6*10	4PCS
A		S4	


X2




13X2

Step14


X2



Step15



Step16



Step17

DIY LED

