



Diagram illustrating assembly instructions and safety warnings:

- Top Warning:** A crossed-out power drill icon indicates that a power drill should not be used for assembly. To the right is a warning triangle with an exclamation mark.
- Time:** A clock icon indicates an estimated assembly time of **10'** (10 minutes).
- Bottom Warning:** A crossed-out icon of a wooden block being cut by a saw indicates that the wood should not be cut. To the right is a warning triangle with an exclamation mark.
- Person:** An icon of a person indicates that **1** person is required for assembly.




**A**




**B**

**A**





**x 1**

**B**





**x 1**

1



2



3

