











Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a rectangular block being placed on a textured surface and a diagram showing the block being secured with a screw.
- Time:** A clock icon is shown next to the text "40'", indicating a 40-minute assembly time.
- Person:** An icon of a person is shown next to the number "1", indicating that one person is required for the assembly.



1

1  x 1	2  x 4	A  M6 x 20 x 16	B  x 16	C  x 1
---	---	---	--	---

