







Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing an L-shaped metal bracket and a crossed-out power drill icon.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a rectangular block being placed on a surface and a crossed-out icon of a block being pushed down.
- Time:** A clock icon is shown next to the text "15'", indicating a 15-minute assembly time.
- Person:** A stick figure icon is shown next to the number "1", indicating that one person is required for assembly.


A



B




A



x 1

B



x 1


C



M4
x
25

x 4

D



x 1

1

