




Installation & Assembly



01:PACKING LIST




02: INSTALLATION KIT

AA	1X	BB	1X	CC	2X	DD	4X
							
mounting Bracket		Ground Screw		Outlet Box Screw		Knurled Nut	
EE	3X	FF	4X	GG	4X	HH	4X
							
Wire Nut		plastic Anchor		Washer		Wood Screw	
II	1X	JJ	52X	KK	216X	LL	88X
							
Gloves		30*120 crystal strips		30# Cube Beads		30*76 crystal strips	
MM	356X	NN	1X				
							
Military-style button		remote control					


AA has already installed the sunshade (A),The three-ring welding frame (D) has been installed on the lamp body (C).

03.Connect the Wires Step

- Step 1: Wrap the ground wire from the oufet box around the Ground Screw (BB) on the Mounting Bracket (AA). and then connect the ground wire from the fture to the ground wire from the outlet box. Step
- Step 2: Connect the wires from the foture to the house supply wires, neutrc1 (white) to neutrc1 wire, and hot (block) to hot wire. Step
- Step 3: Spread apart the wires so that the hot wires are on one sicie of the outlet box aind the neutral wires are on the otheu




- Step 4:Pass Canopy (A) through Mounting Bracket (AA) and secure it with Knurled Nut (DD).




MOUNTING AND WIRE

- Step 1:Install the Mounting Bracket Loosen the Knurled Nut (DD) from the Canopy (A) and remove the Mounting Bracket (AA).




- Step 2:Set the hole position ond insert plastic Anchor(Ff) into the ceiling
- Step 3:Pass Outlet Box screw(CC) through mounting Bracket(AA) and screw into the ceiling box.
- Step 4:Pass Wood Screw(HH) through Washer(JJ) and Mounting Bracket(AA),then tighten into plastic Anchor(Ff)



04. Install the Lamp Body

Step 1: Pass the power cord on the lamp body (C) through the chain (B) and the lampshade (A).

Step 2: Loosen the quick link on Chain (B) and hook it to the rings of Canopy (A) and Hanging Rod (C)



05. Crystal hanging method

Step 1: First, place the MM clasp onto the JJ/MM/LL crystal as shown in the illustration.

Step 2: Then, hang the sealed crystals one by one onto the three-ring welded frame (D).

