





























YOSHI







F15  x...(8)	P25  x...(2)	A1  ø7x50 x...(8)		
G50  6x13 x...(8)	F12  x...(4)	I1  x...(8)	M8  350mm x...(1)	
W1  x...(1)	A6  ø7x40 x...(8)	H4  350mm x...(2)	W2  x...(1)	
K1  ø15x12 x...(12)	P4  x...(8)	C3  Z35PR x...(4)	D3  H=2 PZ35PR x...(4)	G34  3,5x16 x...(70)
K10  x...(12)	B1  ø8x35 x...(20)	I7  x...(12)	L11  x...(2)	N1  M4x9 x...(2)



I





M8

12









G34




G34








II







IV







V




VI




1.




2.







VII




1.





2.




P25





VIII










IX








X

 $a=b$ 






XI









XII




XIII









XIV





XV





XVI

