














USER'S MANUAL

















Parts List




<p>①</p>  <p>2PCS</p>	<p>②</p>  <p>2PCS</p>	<p>③</p>  <p>2PCS</p>	<p>④</p>  <p>1PC</p>
<p>⑤</p>  <p>RIGHT-1PC</p>	<p>⑥</p>  <p>LEFT-1PC</p>	<p>⑦</p>  <p>2PCS</p>	<p>⑧</p>  <p>8PCS</p>
<p>⑨</p>  <p>2PCS</p>	<p>⑩</p>  <p>2PCS</p>	<p>⑪</p>  <p>3PCS</p>	


Hardware List


<p>A</p> <p>M6x45mm</p>  <p>10PCS</p>	<p>B</p> <p>M8x45mm</p>  <p>8PCS</p>	<p>C</p> <p>M6x35mm</p>  <p>12PCS</p>	<p>D</p> <p>M5x25mm</p>  <p>8PCS</p>
<p>E</p> <p>M8</p>  <p>4PCS</p>	<p>F</p> <p>∅8</p>  <p>18PCS</p>	<p>G</p>  <p>1PC</p>	<p>H</p>  <p>1PC</p>






 M6x45mm	
A	6PCS
 ø8	
F	6PCS
	
G	





 M6x45mm	
A	4PCS
 ø8	
F	4PCS
	
G	








	M8x45mm
B	8PCS
	M8
E	4PCS
	∅8
F	8PCS
	G
	H





	
M5x25mm	
D	4PCS

	
G	



	
M6x35mm	
C	6PCS


	
G	






M6x35mm

C 4PCS



G



M6x35mm

C 2PCS






M5x25mm

D 4PCS



G







Connected to bedder sources