













Weight capacity : 100kgs/ 220 Lbs







COMPONENTS LIST


I  Q'TY 1	III  Q'TY 1	VI  Q'TY 2	
II  Q'TY 1	IV 	V  Q'TY 1	VII Left  Q'TY 2 Right  Q'TY 2

HARDWARE LIST


A		14	Screw 7x50	D		4	Screw 4x40
B		2	Screw 7x70	E		2	Allen Key
C		4	Screw 7x90	Supporting tools		Screw driver	




Step 1





Step 2





Step 3




Step 4



Step 5



Step 5



**Please check metal lock , ensure that
it was locked before using**