

















Assembly Instruction







1  1057x237x15 x1	2  800x236x15 x1	3  800x236x25 x1	4  800x236x15 x1
5  1053x235 x1	6  500x81x15 x4	7  1053x235 x1	8  1057x237x15 x1
9  140x38x30 x4	10  140x38x30 x1	11  494x390x12 x2	12  489x135x12 x8
13  489x85x12 x4	14  x4	15  x4	16  494x390x12 x2


A  Φ6X35mm x 14+1	B  Φ15X10mm x 14+1	C  Φ6X30mm x 20+2	D  18X11mm x 8	E  23X10mm x 8
F  Φ5X40mm x 6	G  Φ4X12mm x 20+1	H  Φ4X12mm x 2	I  Φ2X15mm x 30+3	J  27X17mm x 8
K  Φ4X16mm x 4	L  70X65mm x 4	M  Φ4X45mm x 2	N  Φ4X8mm x 8	O  Φ3.5X14mm x 48+3


1





A  x 4	E  x 4	J  x 4
---	--	--

2






A  x 4	E  x 4	J  x 4
---	---	---


3



4




5




B	C
x 4	x 4


6




B	C
x 6	x 6

7




C	F
	
x 6	x 6

8





G	L
	
x 20	x 4



9



10



11



M


M-1

M-2




x 2

12



x2



K

K-1

K-2


O




x 2

x 12


13




x2




14



x2



15




x2

O



x 8

16



D





x 8

N





x 8


17



18



19



20

