









ASSEMBLY INSTRUCTION


DINING TABLE WITH 6 BEADED LEGS

A Table Top  1 pc	B Leaf  1 pc	C Right Support Leg  2 pcs	D Left Support Leg  2 pcs
E Center Support Leg  2 pcs	F Long Stretcher  2 pcs	G Short Center Stretcher  2 pcs	H Allen Bolt Ø5/16"x55mm  14 pcs
I Lock Washer Ø5/16"x11mm  12 pcs	J Flat Washer Ø5/16"x19x1.5mm  12 pcs	K Allen Key 4mm  1 pc	L Screw #8*45mm  6 pcs
M Barrel Nut Ø5/16"x15mm  2 pcs			




This page lists all the contents included in the box. Please take the time to identify the hardware as well as the individual components to this product. As you unpack and prepare for assembly, place the contents on a carpeted or padded area to protect them from damage.


- 1** Attached Right Support Leg(C) and Left Support Leg(D) to the Table Top(A). Attached Long Stretcher(F) to Right Support Leg(C) and Left Support Leg(D). Use Allen Bolt(H), Lock Washer(I) and Flat Washer(J) on holes of Table Top(A). Turn the Allen Key(K) in Allen Bolt(H).




- 2** Attached Center Support Leg(E) to the Table Top(A). Attached two Short Center Stretcher(G) to the Center Support Leg(E). Use Allen Bolt(H), Lock Washer(I) and Flat Washer(J) on holes of Table Top(A). Turn the Allen Key(K) in Allen Bolt(H).




- 3** Attached Short Center Stretcher(G) to Long Stretcher(F). Use Barrel Nut(M) and Allen Bolt(H). Turn the Allen Key(K) in Allen Bolt(H).




- 4** Screwing Short Center Stretcher(G) to Center Support Leg(E), Long Stretcher(F) to Right Support Leg(C) and Left Support Leg(D) with Screw(L).




5 Open the Sash Lock.




6 Put out Table Top(A) each side.




7 Attached Leaf(B) to Table Top(A), push two side tops that reach the Leaf(B).



8 Lock the Leaf(B) by using Sash Lock.



-
- 9** Adjusted the Leveler at the bottom of Leg(E,C,D) to keep the table level.



Cleaning & Care

Treat surface with care. Surface is resistant to scratches but is not scratch resistant. Clean surfaces with a dry or damp soft cloth. Do not use abrasive cleaners. Hardware may loosen over time. Periodically check that all connections are tight.