














Ax15		$\frac{1025}{40.4}$	Bx15		$\frac{1025}{40.4}$
Cx4			Dx8		$\frac{950}{37.4}$
Ex87		$M6x \frac{30}{1.2}$	Fx2		$\frac{1600}{63.0}$
Gx6		$\frac{1600}{63.0}$	Hx4		
Ix2			Jx2		
Kx1			Lx1		$\frac{1644}{64.7}$
Mx1		$\frac{1644}{64.7}$	Nx4		
Ox1		$\frac{1460}{57.5}$	Px1		$\frac{1460}{57.5}$
Qx2			Rx1		
Sx2			Tx1		
Ux3			Vx1		
Wx10		$M6x \frac{40}{1.6}$	Yx1		$\frac{1371}{54.0}$
Zx1		$\frac{1371}{54.0}$	AAx1		$\frac{1371}{54.0}$
ABx1		$\frac{1371}{54.0}$	ACx4		
ADx2			AEx4		
AFx4			AGx2		
T1x1					




Ax6	
Bx6	
Cx4	
Dx4	
Yx1	
Zx1	
AAx1	
ABx1	
ACx6	
AEx4	
Ex28	









Tx1	T1x1	Ux2





Ux1	Vx1
	