

Assembly Instructions





Conference Table

Assembly Instructions:




1. Carefully read these instructions and keep them for future reference.
 2. Refer to the parts list for guidance and ensure that you have all the pieces before starting the assembly process, if anything is missing, damaged, incorrect, contact us **FIRSTLY BEFORE** assembling.
 3. When assembling, place all parts on a soft, clean, and flat surface, such as a carpet, to prevent any scratches.
 4. To avoid misalignment of the holes, Please don't full tighten the screws until you ensure all parts in place.
-




X2



When using the electric screwdriver ,
Reduce the power and torque to avoid damaging the furniture






 Caution

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for free replacement if having damaged or missing parts.

Parts & Hardware List



① 4pcs



② 2pcs



③ 2pcs



④ 1pc




⑤ 2pcs



⑥ 2pcs






⑦ 2pcs




⑧ 1pc

Hardware List


 M6×12mm	 M6×40mm	 M6×60mm	
Ⓐ ×16pcs+1pc	Ⓑ ×12pcs+1pc	Ⓒ ×28pcs+1pc	Ⓓ ×4pcs
		 M6×35mm	
Ⓔ ×2pcs	Ⓕ ×8pcs+1pc	Ⓖ ×4pcs+1pc	Ⓗ ×4pcs+1pc

1




	
M6×12mm	
Ⓐ ×16pcs	Ⓓ ×4pcs

2





M6×40mm
Ⓑ ×8pcs

3




pre-drill 70%




	
M6×40mm	M6×60mm
B ×4pcs	C ×8pcs

4





pre-drill 70%




	
M6×35mm	
G ×4pcs	H ×4pcs

5



6



screw down

