


Assembly Instruction

①




X1

②



X1

③




X1

④




X1

⑤




X1

⑥



X1

⑦



X10

M6×30


⑧



X10

M6 spacer

⑨



X1

Wrench

