ASSEMBLY INSTRUCTION At least 2 people are required for product assembly STEP 1 STEP 2 0 3 X1 **X1** X1 B 8pcs 1pc 8pcs M8*35mm