











<b>T</b>  ∅8*30 x4	<b>U</b>  M6*35mm x5	<b>V</b>  M6*30mm x12	<b>W</b>  M6*25mm x6	<b>X</b>  M6*8mm x17
<b>Z</b>  x4	<b>Za</b>  x4	<b>Zb</b>  ST4*30mm x4	<b>Zc</b>  x6	<b>Zd</b>  4mm x1

Attention: Please do not tighten screws until all screws are well in position!


Attention: Veuillez ne pas serrer les vis tant que toutes les vis ne sont pas complètement insérées!

Achtung: Ziehen Sie die Schrauben erst an, wenn alle Schrauben richtig positioniert sind!


Atención: no apriete los tornillos hasta que todos los tornillos estén bien en su posición!

Attenzione: non stringere le viti finché tutte le viti non sono ben posizionate!


1





2



3





6



Suggestion: the length of the screwdriver is less than 10cm

