

CARE AND MAINTENANCE





For cleaning of the frame, use a mild, soapy water, then dry the surface immediately with a clean, soft cloth. For glass, dust with a soft, dry cloth. Do not use abrasive cleaner.

To use of washing powder or any other substances containing abrasives may scratch the glass.

NOTICE

- * Please make sure that you have all parts indicated before you begin assembly of this item
- * This item should be assembled on a soft surface to prevent scratching the finish during assembly

Part List and Hardware List

PIECE	DESCRIPTION	PICTURE	QUANTITY
A	Stainless Steel Frame		1X
B	Clear Glass Top		1X
HW1	Hexagon Socket Screws 6*0.5*10mm		5X
HW2	Allen Key		1X

DIMENSIONS: 47.24"L x 23.62"W x 30.71"H








WEIGHT CAPACITY: 150 LBS

WARNING: DO NOT STAND ON TABLE
WARNING: DO NOT OVER TORQUE BOLTS/SCREWS

The hardware is hang on the side leg

PREPARATION

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.
If any part is missing or damaged, do not attempt to assemble the product.
Estimated Assembly Time: 10 minutes.
Tools Required for Assembly (included): Allen Key

		
STEP1 PUT CLEAR GLASS TOP(B) FACE DOWN AS PICTURE ON A CLEAN, NON-MARRING SURFACE	STEP2 TAKE OUT THE HARDWARE	STEP3 PLACE AND POSITION THE STAINLESS STEEL FRAME(A) ONTO THE CLEAR GLASS TOP(B)
		
STEP4 AFFIX THEM TOGETHER BY USING 4PCS OF BOLTS WITH ALLEN KEY, THE REMAINING 1 BOLT IS SPARE PART	STEP5 TURN THE TABLE RIGHT SIDE UP. CHECK FOR STABILITY. ENSURE ALL BOLTS ARE FULLY LOCKED AND SECURED INTO POSITION. YOUR TABLE IS NOW READY FOR USE	
The hardware is hang on the side leg		