









#### IMPORTANT INFORMATION:



- 1 ) REMOVE THE PROTECTIVE FOIL IF THE TABLE IS IN HIGH GLOSS
- 2 ) HIGH GLOSS SURFACE HARDENING TIME IS 2 HOURS
- 3 ) AFTER 2 HOURS, TO CLEAN THE SURFACE, USE ONLY SOFT CLOTHS (E.G. COTTON OR MICROFIBRE CLOTHS AVAILABLE IN STORES). WASH THE SURFACE WITH A 1% MIXTURE OF SOAPY WATER


L		M	
7 x 50	x20	x20	

G		H	
x10		x4	



A		B	
7 x 70	x12	8 x 30	x8

I		J	
4 x 15	x8	6,3 x 13	x30


K		E	
x1		x1	

F			
x1			


I




II




III




IV




V




VI



VII



VIII



IX

