





























## DESK Hardware List

ITEM	PART	QTY	ITEM	PART	QTY
A		1pc	H		10pcs
B		1pc	I		14pcs
C		4pcs	J		12pcs
D		12pcs	K		1pc
E		12pcs	L		8pcs
F		8pcs	M		1pc
G		8pcs	N		1pc


# Part List

ITEM	PART	QTY	ITEM	PART	QTY
1		1pc	8		1pc
2		1pc	9		1pc
3		1pc	10		1pc
4		1pc	11		1pc
5		1pc	12		1pc
6		1pc	13		1pc
7		1pc			


# STEP 1




# STEP 2




# STEP 3




# STEP 4



# STEP 5



# STEP 6



# STEP 7

