


Assembly Instructions



Keep these instructions for future reference

WARNING

Read instructions carefully. Check no parts are missing.

Assemble the furniture on a soft level surface to avoid damaging the furniture or your floor.

Carefully identify each component, especially those that are similar.


The most common mistake is getting things back to front.

Separate and identify each component from the hardware pack and rest each one in it's proper location before fastening.

We recommend furniture be assembled near where they will be placed, to avoid moving the product unnecessarily once assembled.



If there is a need to move the furniture, please remove all loose items and have extra hands to help lift the furniture to the desired location. Dragging the furniture will damage both the furniture and the floor.

Regularly check and re-tighten (if necessary) all bolts on furniture that you have assembled yourself.




ALLOW 60 MIN


2 Persons Required



DO NOT USE ON PRODUCT














Tools Required









CHECKLIST





A <input type="checkbox"/>  $\varnothing 6 \times 35$ mm Ax10	B <input type="checkbox"/>  $\varnothing 15$ mm Bx10	C <input type="checkbox"/>  $\varnothing 8 \times 32$ mm Cx40	D <input type="checkbox"/>  $M12 \times 35$ mm Dx6	E <input type="checkbox"/>  $M7 \times 50$ mm Ex6
F <input type="checkbox"/>  L4 Fx1	G <input type="checkbox"/>  $9 \times 10 \times 14$ mm Gx10	H <input type="checkbox"/>  $M3.5 \times 15.5$ mm Hx10	I <input type="checkbox"/>  $\varnothing 5 \times 15$ mm lx12	J <input type="checkbox"/>  $\varnothing 8$ mm Jx3
K <input type="checkbox"/>  $25 \times 25 \times 2$ mm Kx4	L <input type="checkbox"/>  $\varnothing 9.5 \times 15$ mm Lx4	M <input type="checkbox"/>  $\varnothing 11 \times 16$ mm Mx4		

1




2



3



Bx6




4




Ex6



Fx1




5



Ax4




Cx20



6




Bx2



7




Bx2



8




Cx4




9



Dx6



Kx4





10



Gx10




Hx10



11



1x12




12



Lx4



Mx4






x 2

10-11

13



Jx3



14

