

Assembly Instructions



Parts List



label	Picture	Qty
A		1
B		4
C		1
T - 1	(M6X12)	8
T - 2	(M4X20)	16
T - 3		1

Assembly Steps



ATTENTION:

DO NOT COMPLETELY TIGHTEN ANY SCREWS UNTIL ALL PARTS ARE IN PLACE

Step 1



Step 2



Step 3

