
ASSEMBLY INSTRUCTION

Step 1:



Finish:



Hardware List:

No.:	Description	Drawing	Size	Q' ty
Α	Middle Bolt	(Communication	Ø5/16" X2-1/4 "	4
В	Lock Washer	6	Ø5/16" X12mm	9
С	Flat Washer	0	Ø5/16" X22mm	9
D	Long Bolt	(Carrieraniana)	Ø5/16" X3-1/2 "	4
E	Short Bolt	Canana	Ø5/16" X1-3/4 "	1
F	Allen Wrench		5mm	1