Safety Tips

Please read the following content before installation:

- 1\. Ensure that the desktop material is suitable for punching holes (wood, density board, etc., glass or metal requires special tools).
- 2\. When drilling, avoid damaging the wires or equipment below the desktop.
- 3\. It is recommended that two people collaborate on installation to prevent the drawer from slipping.

Installation steps

Step 1: Locate the punching position

- 1\. Attach the drawer slide rail * * tightly to the bottom of the desktop * *, and confirm the installation position (recommended 5-10cm away from the edge of the table).
- 2\. Use a pencil to mark * * 4 screw hole positions * * (2 holes on each side of the slide rail, symmetrical in front and back).
- 3\. Use a tape measure to check if the holes on both sides are aligned horizontally.

Step 2: Drilling

- 1\. Choose a drill bit that matches the screw (usually 4mm).
- 2\. Drill a vertical hole at the marked position, with a depth slightly longer than the length of the screw (to avoid drilling through the tabletop).

Step 3: Secure the slide rail

- 1\. Align the slide rail with the hole position and preliminarily tighten it with screws (do not completely lock it).
- 2\. After adjusting the slide rail to a horizontal position, thoroughly tighten all screws.

Debugging and maintenance

Common problem handling

-Drawer tilt: Check if the sliding rails on both sides are aligned horizontally, loosen and adjust again.

Cleaning suggestions

Regularly wipe the slide rail with a dry cloth to avoid dust accumulation that may affect its use.

Precautions

! Do not forcefully push the drawer to prevent deformation of the slide rail.