


ASSEMBLY INSTRUCTION





PARTS LIST

A	B	C	D	E	F
X1	X1	X2	X1	X2	X1




HARDWARE LIST

150X60X50mm	M8X60	M5	M5X50	
1	2	3	4	5
X3	X3	X1	X6	X3


BOX1




BOX2




Step1




Step2




Step3




Step4





Step5




Step6



Step7



ASSEMBLY INSTRUCTION




PARTS LIST


A X1	B X1	C X1	D X1	E X1	F X1

HARDWARE LIST


1 X4	G X1




Step 1




Step2




Step3




Step4





Step5




Step6



Step7



ASSEMBLY INSTRUCTION





PARTS LIST

A	B	C	D	E	F
X1	X1	X2	X1	X2	X1




HARDWARE LIST

150X60X50mm	M8X60	M5	M5X50	
1 X3	2 X3	3 X1	4 X6	5 X3


BOX1




BOX2




Step1




Step2




Step3




Step4





Step5




Step6




Step7



ASSEMBLY INSTRUCTION



PARTS LIST



A


X1



B

X1


HARDWARE LIST



150X60X50mm

1

X4



M8X60

2

X4



M5

3


X1





M5X50


4

X8



- ①  X4
- ②  X4
- ③  X1
- ④  X8

Step1



Step2

