


CARE AND MAINTENANCE

Spot clean using a mild water-free solvent. Only a professional cleaner should undertake a complete overall cleaning.  
The use of steam or water-based cleaners may cause excessive shrinking or staining.

NOTICE

- \* Please make sure that you have all parts indicated before you begin assembly of this item.
- \* This item should be assembled on a soft surface to prevent scratching the finish during assembly.
- \* This item may require periodic tightening.








Product Dimensions: 42"W x 20"D x 30"H






WEIGHT CAPACITY :  
TOP : 110 LBS

WARNING: DO NOT OVER TORQUE  
BOLTS/SCREWS



Part List and Hardware List

PIECE	DESCRIPTION	PICTURE	QUANTITY
A	TOP PANEL		1X
B	FRONT LEFT LEG		1X
C	BACK LEFT LEG		1X
D	FRONT RIGHT LEG		1X
E	BACK RIGHT LEG		1X
F	SUPPORT LEG		2X
G	STRETCHER		1X

PIECE	DESCRIPTION	PICTURE	QTY
1	60 MM BOLT	M6x60mm 	6X
2	50 MM BOLT	M6x50mm 	8X
3	SPRING WASHER		14X
4	FLAT WASHER		14X
5	ALLEN KEY		1X



**PREPARATION**

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.  
If any part is missing or damaged, do not attempt to assemble the product.  
Estimated Assembly Time: 60 minutes.  
Tools Required for Assembly : Phillips Screwdriver

	
<p><b>STEP 1</b> ATTACH BACK LEFT AND BACK RIGHT LEGS TO STRETCHER USING 60 MM BOLTS, SPRING WASHERS AND FLAT WASHERS. TIGHTEN THE BOLTS USING ALLEN KEY.</p>	<p><b>STEP 2</b> ATTACH SUPPORT LEGS TO UNIT USING 60 MM BOLTS, SPRING WASHERS AND FLAT WASHERS. TIGHTEN THE BOLTS USING ALLEN KEY.</p>

**PREPARATION**

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.  
If any part is missing or damaged, do not attempt to assemble the product.  
Estimated Assembly Time: 60 minutes.  
Tools Required for Assembly : Phillips Screwdriver

 <p>The diagram shows a side view of the assembly process. A horizontal bar, labeled 'D', is being attached to a vertical leg. A bracket, labeled 'B', is also shown. Hardware is indicated by numbers 1, 3, and 4. A circular inset shows a close-up of the bracket 'B' being secured to the leg with a bolt and washer.</p>	 <p>The diagram shows a top-down view of the assembly. A horizontal bar, labeled 'A', is being attached to the top panel. Hardware is indicated by numbers 2, 3, and 4. A circular inset shows a close-up of the hardware (bolts, spring washers, and flat washers) being used to secure the bar to the top panel.</p>
<p><b>STEP 3</b> ATTACH UNIT TO FRONT LEFT AND FRONT RIGHT LEGS USING 60 MM BOLTS, SPRING WASHERS AND FLAT WASHERS. TIGHTEN THE BOLTS USING ALLEN KEY.</p>	<p><b>STEP 4</b> ATTACH UNIT TO TOP PANEL USING 50 MM BOLTS, SPRING WASHERS AND FLAT WASHERS. TIGHTEN THE BOLTS USING ALLEN KEY.</p>


## PREPARATION

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.

If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 60 minutes.

Tools Required for Assembly : Phillips Screwdriver



**STEP 5** ADJUST THE ADJUSTER THAT HAS ALREADY BEEN ASSEMBLED TO THE LEGS TO STABILIZE YOUR UNIT.