
Learniture

LNT-RIA3052-SO

1-800-260-2776



Note: Remove orange cap prior to connecting to underside of

seat, or damage will occur.

Note: Connect end with larger opening to underside of seat.

