


CORNER GAZEBO WITH SUN VISOR 1014

If you have any questions about the outdoor gazebo, please feel free to contact us.
Customer Service Email: Service@alaulm.com




P25109-D1

IMPORTANT

PLEASE READ BEFORE YOU COMMENCE ASSEMBLY

Follow the guidelines in this user guide to ensure correct
assembly and care for this product.

SPECIFICATIONS



Catalog

Specifications..... 01

Notice And Warning 03

Part List 05

Instruction 08

NOTICE


Note: The gazebo needs to be installed in cooperation with five people. The following tools are not included and needed for assembly:



Pistol Drill




Tape Measure




Hammer



Screw Driver



2 m Adjustable Ladder



5 people

Warning

1. A 5 personal assembly is required for this gazebo.
2. Please take appropriate actions as heavy rain, wind and snow can damage the gazebo. If necessary please disassemble and store it for later use.
3. In snowy conditions, please do not allow the thickness of the snow to be more than 1.82 inches on the roof, this should be cleared as soon as possible for your safety. When the wind speed reaches 38.49 km/h, please take measures to avoid the wind.

PLEASE RETAIN THESE INSTRUCTIONS FOR FUTURE REFERENCE.

Dear Customer,


Thank you for shopping with us!

When you receive the product, please make sure that all the parts are intact. Then please browse the entire installation manual before assembling.

If any problem occurs unsatisfactorily as follows:





- A.The outer box is damaged
- B.The product is damaged / bent / cracked while you open the box
- C.The parts / accessories / assembly tools are missing
- D.The product is hard to assemble
- E. The instructions are not clear and can not be referred
- F.The product has functional problems
- G.Other aspects that you are not satisfied with

Please feel free to contact us for help. Our after-sales team service (**Service@alaulm.com**) will reply within 24 hours and will do our best to resolve the problem for you.

















**Attention:**

- 1.Please fix all the screws first,do not lock them off,after assembling is fully completed, lock all at once finally.
- 2.Please check the manual carefully and make sure you have received all the parts.
- 3.If there is any missing,please let us know the letter of the parts you need.
- 4.If there is any damage,please send clear photos to us,and we will check and offer you best solution soon.





PARTS LIST

Parts List				
A1 	A2 	A3 	A4 	A5 
1 PC	2 PCS	1 PC	1 PC	1 PC
B1 	B2 	B3 	B4 	B5 
1 PC	1 PC	1 PC	1 PC	1 PC
B6 	B7 	B8 	B9 	B10 
1 PC	1 PC	1 PC	1 PC	1 PC
C1 	C2 	C3 	C4 	D1 
1 PC	1 PC	1 PC	1 PC	2 PCS
D2 	D3 	D4 	E1 	E2 
2 PCS	1 PC	1 PC	1 PC	1 PC

PARTS LIST

Parts List				
E3 	E4 	F1 	F2 	G 
1 PC	1 PC	6 PCS	6 PCS	7 PCS
G1 	H 	I 	I1 	K 
14 PCS	2 PCS	12 PCS	2 PCS	4 PCS
K1 	K2 	L 	L1 	L2 
4 PCS	1 PC	2 PCS	2 PCS	2 PCS
L3 	M 	M1 	M2 	N 
2 PCS	2 PCS	3 PCS	3 PCS	4 PCS
N1 	O 	O1 	O2 	O3 
20 PCS	2 PCS	3 PCS	12 PCS	4 PCS
P 	R 	R1 	R2 	R3 
2 PCS	14 PCS	1 PC	1 PC	1 PC

PARTS LIST

Parts List				
R4 	S 	U 	V 	
1 PC	2 PCS	4 PCS	4 PCS	
Screw Set				
Q 	Q1 	Q2 	Q3 	Q4 
12 PCS	68 PCS	8 PCS	224 PCS	24 PCS
1 	2 	3 	4 	5 
M6*15	M6*15	M6*28	M6*45	M6*50
12 PCS	184 PCS	8 PCS	8 PCS	24 PCS
6 	7 	8 	9 	10 
24 PCS	1 PC	24 PCS	8 PCS	10 PCS
11 	12 	13 	14 	
16 PCS	10 PCS	1 PC	1 PC	


1. Please ensure that all accessories are complete before starting the installation.

2. Due to the variety of accessories, many accessories may be glued together, please check carefully


3. If any accessories are missing or damaged, please contact the seller immediately.

E-Mail: Service@alaulm.com


STEP 1




A1 1x



A2 2x






A3 1x



K 4x




P 2x



2 X32	Q3 X32
 M6*15	





STEP 2



L1 2x



L3 2x










2 X4



Q3 X4







STEP 3




2 X4	Q3 X4
 M6*15	

STEP 4










D1, D2, D3, and D4 each have two rows of hooks, with five hooks in each row.














Q X12	Q1 X68

STEP 5




2 X11  M6*15	3 X2  M6*28	Q3 X13 
--	---	---

STEP 6




(2) X11	(3) X2	Q3 X13
M6*15	M6*28	


STEP 7




B5 1x










B6 1x



K1 1x



N1 6x



1 X12



M6*15

2 X10



M6*15

Q3 X10



STEP 8

B7 1x

B8 1x


B9 1x

B10 1x

K1 1x

K2 1x

N1 8x



2 X34
M6*15

Q3 X18


STEP 9



M1 2x



M2 2x



2 X16	8 X16	Q3 X16
 M6*15		


STEP 10




M1 1x



M2 1x




N 2x




2 X12	4 X4	8 X8	Q3 X12
M6*15	M6*45		


STEP 11



O 2x




O1 3x



3 X4 M6*28	12 X10	Q2 X8	Q3 X4
-----------------------------------	-------------------------------	------------------------------	------------------------------

STEP 12






- 
E1 1x
- 
E2 1x
- 
E3 2x
- 
E4 1x
- 
I1 2x
- 
N 2x



 X10	Q3 X10
 M6*15	


STEP 13


X6




(2) X6  M6*15	(5) X24  M6*50	(6) X24 	Q3 X30 	Q4 X24 
--	---	---	--	--

STEP 14




2 X28	4 X4	Q3 X16
 M6*15	 M6*45	


STEP 15




(R1) 1x





(R2) 2x



(R3) 1x




(R4) 2x








STEP 16



G 7x



R 14x



Due to gaps in the assembly holes, if the clearance between the PC board R and the tube is too large or too small during assembly, loosen the outermost screw securing N. Adjust the tilt angle of N appropriately, then tighten the screw to ensure smooth completion of the PC board R assembly.

Q3 X36

0

STEP 17



G1 14x




H 2x



O2 12x



O3 4x



2 X4



M6*15

11 X16




Q3 X4



STEP 18




S 2x




2 X2  M6*15	9 X8 	10 X10 	Q3 X2 
--	--	--	---





STEP 19




U 4x



V 4x





www.alaulm.com

Make your life much better.