









X2

1




1100*200*15mm 1 PC

2




1079*183*15mm 1 PC

3




1005*183*15mm 1 PC

4



1005*183*15mm 1 PC


5




620*183*15mm 1 PC

6

one side




turn over



the other side


620*183*15mm 1 PC

7




845*383*15mm 1 PC

8



845*383*15mm 1 PC

9



one side



turn over




the other side

765*383*15mm 1 PC


10

one side



turn over


the other side




765*383*15mm 1 PC

11

one side




turn over



the other side


1110*400*15mm 1 PC

12



1079*383*15mm 1 PC


13



370*183*15mm

1 PC


14



347*60*15mm

2 PCS


15



355*60*15mm

3 PCS


16



717*60*15mm

2 PCS


17



1079*65*15mm

2 PCS


18



157*367*15mm

2 PCS

19




300*90*15mm

2 PCS

20


one side



300*90*15mm

2 PCS


21



300*90*15mm

2 PCS


22



637*367*15mm

3 PCS


23



734*367*15mm

2 PCS


24



354*367*15mm

1 PC


25



345*150*15mm

2 PCS


26



345*350*15mm

2 PCS


27



629*356*3mm

2 PCS


28



629*363*3mm

1 PC


29



378*357*3mm

1 PC


30



774*356*3mm

2 PCS


31



774*363*3mm

1 PC


32



310*295*3mm

2 PCS


33



715*368*3mm

1 PC


A



A1


ø7*40mm

A2




ø15*9.5mm 66PCS

B




ø8*30mm 32PCS

C




ø8*50mm 3PCS

D




M3.5*14mm 124PCS

E



M3.5*14mm 4PCS


F



M3.5*35mm 8PCS

G


Full Overlay



φ35mm 8PCS


H

Half Overlay



φ35mm 4PCS

I




I1




I2

1PC


J




16PCS




28PCS




N1



N2



N3




N4



N5

2PCS



10PCS

P




ø21mm

66PCS


Q



Q1



Q2



Q3



Q4*2



Q5*2


1PC

Hardware installation demonstration




NOTE: Please make sure
"A1" hardware tightened
and can't be pulled out!


I






II



III




STEP 1




	A1 × 2PCS
---	-----------

STEP 2




	A2 × 2PCS		B × 2PCS
---	-----------	---	----------


STEP 3



STEP 4




STEP 5




	A1 × 4PCS
---	-----------

STEP 6




	A2 × 4PCS		B × 3PCS
---	-----------	---	----------

STEP 7




	A2 × 4PCS		B × 1PC
---	-----------	---	---------

STEP 8




STEP 9




	A1 × 2PCS
---	-----------

STEP 10




	A2 × 2PCS		B × 1PC
---	-----------	---	---------

STEP 11




STEP 12




	A1 × 8PCS
---	-----------


STEP 13




STEP 14



STEP 15




STEP 16



	A2 × 3PCS
	B × 2PCS
	C × 1PC

STEP 17

one side




10

A1

turn over

the other side



10


A1

D

CR

	A1 × 4PCS
	D × 6PCS
	CR × 2PCS

STEP 18



9

10

15


A2

B

C


	A2 × 3PCS		B × 2PCS		C × 1PC
---	-----------	---	----------	---	---------

STEP 19




	A1 × 4PCS
---	-----------

STEP 20




	A2 × 4PCS
	B × 2PCS

STEP 21




	A1 × 5PCS
---	-----------

STEP 22




	A2 × 3PCS
	B × 3PCS

STEP 23




	A2 × 3PCS		B × 1PC
---	-----------	---	---------

STEP 24




	A2 × 1PC
---	----------

STEP 25




	A1 × 5PCS
---	-----------

STEP 26




	A2 × 5PCS		B × 4PCS
---	-----------	---	----------

STEP 27




STEP 28



	A1 × 14PCS		I1 × 1PC		I2 × 2PCS
---	------------	---	----------	---	-----------

STEP 29




	A2 × 8PCS
	B × 4PCS

STEP 30



	0 × 10PCS
---	-----------


STEP 31



	A2 × 6PCS
	B × 3PCS
	P × 58PCS

STEP 32


X2



	A1 × 4PCS
---	-----------

STEP 33


X2



	F × 4PCS
---	----------


STEP 34

X2



STEP 35


X2




	A2 × 4PCS
	P × 4PCS

STEP 36


X2



STEP 37





STEP 38



	D × 4PCS
	H × 2PCS


STEP 39



	D × 4PCS
	G × 2PCS

STEP 40


Half Overlay




	D × 4PCS
	H × 2PCS

STEP 41


Full Overlay X2








	D × 4PCS
	G × 2PCS

STEP 42





First , Regulating gap







Second , Lock screw



Cabinet door up and down fine adjustment



Cabinet door left and right fine adjustment




Fine-tune the gap after the cabinet door is closed








D × 32PCS

STEP 43





First , Regulating gap







Second , Lock screw



Cabinet door up and down fine adjustment



Cabinet door left and right fine adjustment




Fine-tune the gap after the cabinet door is closed




D × 16PCS


STEP 44



STEP 45








STEP 46







This step is very important to prevent the product from shaking.



	D × 28PCS
	M × 28PCS

STEP 47




 		 		N1 × 4PCS	
		 		N2 × 4PCS	
		 		N3 × 4PCS	
		 		N4 × 4PCS	
		 		N5 × 2PCS	

STEP 48



E × 4PCS

STEP 49



Make sure the arrows are in the same position !

Q1 and Q2 are connected;
Q2 and I1 are connected;

Last: Plug the Q2 into the power supply !
Q3 can be adjusted !

	Q2 × 1PC
	Q3 × 1PC
	L × 2PCS

END

