













Assembly Instruction




PARTS LIST




NO.	QTY.	LINEDRAWING
(A)	50	 7x50mm
(B)	10	
(C)	10	
(D)	10	 8x40mm
(E)	2	
(F)	12	
(G)	24	 3.5x14
(H)	4	
(I)	66	
(J)	10	

NO.	QTY.	NO.	QTY.
(1)	2	(10)	2
(2)	1	(11)	1
(3)	1	(12)	1
(4)	1	(13)	1
(5)	1	(14)	2
(6)	4		
(7)	2		
(8)	2		
(9)	1		


1




2




3




4




5




6




7




8



9



10



11

