















Assembly Instruction

NO	PARTS	QTY
A		1 PC
B		1 PC
C		2 PCS
D		3 PCS
E		3 PCS
F		4 PCS
G		1 PC
H	 $\Phi 8*30$	8 PCS
I		4 PCS
J		5 PCS
K		4 PCS
L		1 PC


STEP 1




STEP 2



STEP 3



STEP 4



STEP 5

