




# ORIGINAL INSTRUCTION MANUAL



















## DEAR CUSTOMER,











Thank you for choosing our product. Please read this manual carefully before assembling or using the product, to avoid damage caused by improper use. If the product is passed on to third parties, this manual has to be passed on along with the product. For any question don't hesitate to contact us



# PARTS LIST

1	1×	2	1×	3	2×
					
4	4×	5	4×	6	2×
					
7	1×	8	16×	9	12×
					
10	4×	11	2×	12	2×
					
13	2×	14	4×	15	2×
					
					2×
					16


# Hardware LIST





<b>A</b> 4×  M8×50mm	<b>B</b> 12×  M8×20mm	<b>C</b> 8×  M6×40mm
<b>D</b> 12×  M6×35mm	<b>E</b> 36×  M6×15mm	<b>F</b> 12× 
<b>G</b> 1×  M6	<b>H</b> 1×  M8	<b>I</b> 1×  M6
<b>J</b> 2× 		

# ASSEMBLY


Before your installation, please make sure that you have all the parts listed on the manual. If you find something missing, stop installing and contact your supplier immediately.



1




	<b>E</b> X4PCS
	<b>I</b> X1PCS
	<b>B</b> X4PCS
	<b>H</b> X1PCS

2








	<b>A</b> X4PCS
	<b>G</b> X1PCS

**3**





**4**


	<b>8</b> X8PCS
	<b>9</b> X8PCS
	<b>E</b> X16PCS
	<b>I</b> X1PCS





**5**


	<b>B</b> X8PCS
	<b>H</b> X1PCS

5





6

	<b>E</b> X16PCS
	<b>I</b> X1PCS




6







	<b>C</b> X8PCS
	<b>I</b> X1PCS

**7**






**8**


	<b>D</b> X4PCS
	<b>F</b> X4PCS
	<b>G</b> X1PCS







**7**


9

	<b>D</b> X8PCS
	<b>F</b> X8PCS
	<b>G</b> X1PCS




10

	<b>J</b> X2PCS
	<b>15</b> X2PCS
	<b>16</b> X2PCS
	<b>G</b> X1PCS



11



12

