



















ASSEMBLY INSTRUCTION






Parts List:




Hardware List:

 Ax20	 Bx20	 Cx28	 M4x35mm Dx14	 M3x14mm Ex4	 M3x12mm Fx2
 M4x16mm Gx2	 Hx2	 Ix2	 Jx2	 Kx12	 Lx4
 M6x60mm Mx6	 Nx2	 Ox1	 M4x25mm Px6		


1




2



3




4




5

90°




6




x2


7




8




9




10




11





12




13



14



15



16

