

# Stand-up desktop computer desk

Please read this manual before you start installing and assembling this product. If you have any questions or ambiguities about the instructions and warnings, please contact us for assistance.

note:

1. Please do not exceed the rated load, otherwise it will cause damage to the monitor or personal injury.
2. Be sure to follow the instructions in the manual. Improper installation may result in damage to the product or personal injury.
3. Please use our tools and accessories to install, otherwise it will cause damage to the product.
4. Make sure that the support surface can safely support the weight of the support equipment and all accessories.
5. This product contains small parts that can cause serious personal injury if swallowed. Keep out of reach of children.
6. Please do not install the monitor before assembling the workbench.
7. Please do not open or replace the workbench without authorization.
8. This product is for indoor use only. Outdoors can cause damage to the product.



important:

Make sure you have received all the parts based on the list provided before installation. If any parts are missing or damaged, please contact your supplier.


maintain:

Please check the workbench at regular intervals (at least every three months) to see if the workbench is stable and there are any screws that fall off due to long-term use. If there is a safety hazard, please replace the accessories or harden the installation in time.

**Desktop Weight  
Capacity  
17kg(37lbs)**




1



1400X500

X1


2



1000X500

X1


3



1130X150

X1


4



1130X113

X1


5



750X150

X1


6



947.5X150

X1


7



450X240


X1

8



X1

9



X1

10



25X25X720

X1


11



25X25X720


X1

12




X1

13




X1

14



X1


15



25X25X1130

X1


16



25X25X1130

X1


17



20X40X930

X1


18



25X25X950

X1


19



25X25X250

X1


20



Φ19


X3

21




X2

22




X2

23




X1

24




M8

X8



M6


X4



X1

A


M6X70



X2

B


M6X60



X26

C


M6X45



X7

D

M6X35



X4

E


M6X25



X20

F


M6X12



X18

H

M5X60




X2


I

M6Nut

(1)




(2)



(3)

Figure (1)-10

Figure (1)11




(4)


Figure (2)

Figure (1)-12


Figure (3)




(5)




(6)



(7)




(8)







(9)




(10)




(11)




(12)




(13)



(14)



(15)



(16)

