













<p>Ax2</p> 	<p>Bx4</p> 	<p>Cx2</p> 	<p>Dx28</p>  <p>M6x $\frac{15}{0.6}$</p>
<p>Ex28</p> 	<p>Fx24</p> 	<p>Gx3</p> 	
<p>1</p>  <p>A</p> <p>C</p> <p>Dx12 Ex12</p> <p>80%</p>	<p>2</p>  <p>Bx4</p> <p>Dx16 Ex16</p> <p>mm inch</p> <p>x1</p> <p>80%</p>		
<p>3</p>  <p>Fx24</p>	<p>4</p>  <p>80%</p>		
<p>5</p> 