










P4  L=400mm x2	T1  x5	B1  ^B ø17/4-5mm x4	S6  2,5x20mm x20				
N1  L=35mm x20	F1  7x50mm x12	F3  Hex 4mm x1	A1  ZP x4	S1  3,5x16mm x16	Z1  x100	V15  x20	V13  x1
E1  8x30mm x12	M1  12x15mm x20	E5  8x70mm x4	V16  5x16mm x12	V19  x2	V8  L=414mm x1	R1  6x8mm x12	V7  x2




1	x	1
2	x	1
3	x	1
4	x	1
5	x	1
6	x	2
7	x	1
8	x	1


9	x	4
10	x	1
11	x	2
12	x	3
13	x	2
14	x	4
15	x	2
16	x	2


E1	M1	E5	V16
			
8x30mm	x2	12x15mm	x2
8x70mm	x2	5x16mm	x6





E1	M1	E5	V19
			
8x30mm	x2	12x15mm	x2
8x70mm	x2		x1



V19  x1 6x8mm	R1  x4	V7  x2 5x16mm	V16  x6
---	---	---	--





N1  L=35mm x4
--



N1





L=35mm x4




F1


F3




7x50mm x8 Hex 4mm x1






M1	N1	P4	T1	R1
				
12x15mm	x2 L=35mm	x4 L=400mm	x2	x2 6x8mm













M1	N1	P4	T1	R1
				
12x15mm	x2 L=35mm	x4 L=400mm	x2	x2 6x8mm



M1  12x15mm x8	N1  L=35mm x8	T1  x1	E1  8x30mm x8
---	---	--	---










N1







L=35mm x4



B1







ø17/4-5mm x4







Z1



x12





V8

L=414 mm x1

