

Assembly Instruction D1606-52S DAPHNE 5 PC COUNTER SET

(SET INCLUDES COUNTER TABLE & 4 CHAIRS)

Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts, which may have come loose inside the carton during shipment. Identify and count all items and compare with the parts list and/or hardware list shown below.


	PARTS LIST FOR CHAIRS				
No.	DESCRIPTION	SKETCH	Q'TY		
Α	CHAIR BACK		4		
В	SEAT		4		
С	FRONT LEG		8		
D	SIDE STRETCHER		8		
Е	FRONT STRETCHER		4		

HARDWARE LIST FOR CHAIRS					
No.	DESCRIPTION	SKETCH	Q'TY		
1	ALLEN BOLT (5/16" x 3-1/2")	()	16		
2	ALLEN BOLT (5/16" x 2-1/4")	()	20		
3	FLAT WASHER (5/16" x 7/8" x 1/16")	0	36		
4	SPRING WASHER (5/16")		36		
5	ALLEN KEY (M5)	ſ	4		
6	FLAT HEAD SCREW (Ø8 x 1-3/4")	()	24		
7	WOOD DOWEL (Ø10 x 1-1/4")		8		

DO NOT TIGHTEN LEGS UNTIL THE CHAIR IS FULLY ASSEMBLED


STEP 1: Place the chairback (A) on a soft and clean surface. Install the wood dowel (7) to the seat (B) in order to line up the cushion seat (B) with the chair back (A) before assembling the two pieces together by using Allen Key (5) with hardware 2,3 and 4.

**Attention: DO NOT TIGHTEN THE BOLTS.




STEP 2: Assemble the cushion seat (B) with the back legs of the chairback (A) by using Allen Key (5) with hardware 1,3, and 4.

**Attention: DO NOT TIGHTEN THE BOLTS.




STEP 3: Assemble the front legs (C) with the Cushion Seat (B) by using Allen Key (5) with hardware 1, 2, and 4.

**Attention: DO NOT TIGHTEN THE BOLTS.



STEP 4: Install the side stretcher (D) between front leg (C) and the back legs of chairback (A). Then install the front stretcher (E) between the front legs (C). Assemble all the stretchers by using a screwdriver with hardware (4).

**Attention: DO NOT TIGHTEN THE SCREWS






Assembly Instruction D1606-52S DAPHNE 5 PC COUNTER SET

(SET INCLUDES COUNTER TABLE & 4 CHAIRS)

STEP 5: To level the chair, stand the chair up on a flat surface and tighten all the bolts by using Allen Key (5) and all the screws with a screwdriver.



MADE IN VIETNAM



Assembly Instruction D1606-52S DAPHNE 5 PC COUNTER SET

(SET INCLUDES COUNTER TABLE & 4 CHAIRS)


Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts, which may have come loose inside the carton during shipment. Identify and count all items and compare with the parts list and/or hardware list shown below.


PARTS LIST FOR TABLE				
No.	DESCRIPTION	SKETCH	Q'TY	
F	TABLE TOP		1	
G	TABLE LEG		4	

HARDWARE LIST FOR TABLE				
No.	DESCRIPTION	SKETCH	Q'TY	
8	ALLEN BOLT (5/16" x 2-1/4")	())))))))))))))))))))))))))))	8	
9	FLAT WASHER (5/16" x 7/8" x 1/16")	0	8	
10	SPRING WASHER (5/16")	O	8	
11	ALLEN KEY (M5)	ل	1	


DO NOT TIGHTEN LEGS UNTIL THE TABLE IS FULLY ASSEMBLED

STEP 1:





STEP 3: To level the table, stand the table up on a flat surface and tighten all the bolts by using Allen Key (11).



MADE IN VIETNAM