




Assembly Instructions

Holder





Power Driver with
Adjustable Torque

#2 Phillips Head
Driver Bit


#2 Square Head
Driver Bit

Flat Blade
Driver Bit

T-20 Torx Head
Driver Bit

Square

Tape Measure




1

50200 x2




2

50951 x2



3


51708 x4



4


50006 x2

1



50706

Remove paper strips
and place track as
shown below.



Track square
and back $\frac{3}{8}$ "

2

3

Item 51708 **3** may be
substituted for item 50006
4 if tamper resistant is not
required.

4

