



Assembly Instructions




A1




x1

A2




x1

B1




x2

B2



x2

C



x2

D



x2

E




x4

F




x2

G




x1

H



x2

I



x1

J1




x1

J2




x1

K1



x1

K2



x1

L



x 96

M




x16

N




x 8

1




x1

2



x2

3



x1

4



x1

