








# ASSEMBLY INSTRUCTION FOR CABINET

A		Tipping Hardware	1 SET
B		Screwdrivers (Not included)	1 PC







Tipping Hardware

