




Assembly Manual


1/2




X3




X1




X16




X3




X2



X3




X64




X1


A(X3)
B
C(X16)




J 64pcs




X2



X1



X2



64pcs

1pcs

