




60Mins



x2



CUSTOMER FIRST, SERVICE FOREMOST!


Questions? Issues?

CONTACT US

REPLY WITHIN 24 HOURS IN BUSINESS DAYS


A

× 2




B

× 2




C

× 2




D

× 1




E

× 1




F

× 1




G

× 4




H

× 4




I

× 1




J

× 1




K

× 1




L

× 4




M

× 3



N


× 49



M6×35mm

O

× 2



M6×95mm


P

× 51




Q

× 1




R

× 6




1



Note:1. When assembly, do not tighten the screws up 100% one by one first until making sure all the corresponding screws are placed in the right positions and are tighten up 70%.
2.If the screws could not be tighten, please loose it and then tighten again after making the holes line up.





2



× 2

| | | |
|----------|---|------|
| N |  | 4PCS |
| P |  | 4PCS |



3




× 2

| | | |
|----------|--|-----|
| O | | 1PC |
| P | | 1PC |



4



N  3PCS

P  3PCS



5





N  4PCS



P  4PCS



6




| | | |
|----------|---|------|
| N |  | 8PCS |
| P |  | 8PCS |

7



| | | |
|----------|---|-------|
| N |  | 20PCS |
| P |  | 20PCS |

8



9

