








ASSEMBLY INSTRUCTION



















Notice

1. **50% Tighten before fixings all screws, is recommended instead of an electric drill.**
2. **Place the item on a flat ground to adjust and make sure it remains stable.**
3. **Tighten up all screws with tools gradually.**
4. **If the screws are not aligned with holes during assembly, please loosen all the other screws to 50% and continue the assembly process.**
5. **If the item is not stable, please loosen all the screws, adjust it on a flat ground and tighten up all screws again.**
6. **Note: If one or more screws are fully tightened during assembly, chances are the others will not be aligned with holes. In addition, all the holes are designed to be relatively larger to provide more space for the adjustment of the screws.**




Part list & Hardware

A  2 pcs	B  2 pcs	C  2 pcs
D  1 pc	E  1 pc	F  1 pc
G  2 pcs	H  2 pcs	I  1 pc
J  1 pc	K  2 pcs	L  4 pcs
M  5 pcs	N  2 pcs	O  5 pcs
P  1 pc	Q  2 pcs	R  8 pcs


Part list & Hardware

S




1 pc

T




2 pcs

U




2 pcs

V




2 pcs

X




2 pcs

1




**Bolt M6x55 mm
(26 pcs)+extra 2pcs**

2




**Bolt M6x40 mm
(32 pcs)+extra 3pcs**

3




**Bolt M6x30 mm
(82 pcs)+extra 3 pcs**

4



**Nut M6
(26 pcs)+extra 2pcs**

5




Plastic feet (32 pcs)

6




**Plastic connector
(6 pcs)**

7




Spanner (1 pc)

8




Allen key M4 (1 pc)


WF 285787



C*1



B*1




R*8



M*1



P*1




O*2




HARDWARE


WF 285788




C*1



B*1




L*4



Q*2




M*2




O*2


WF 285789




E*1




D*1




N*2




A*2




U*2




S*1



V*2



T*2




X*2




O*1

WF 285790




H*2




I*1




M*2




G*2



K*2





J*1






F*1

STEP 1x2






①*2 ④*2

STEP 2x2






①*4 ④*4

STEP 3x2





③*3

STEP 4x2





③*4

STEP 5x2





②*4 ⑤*4

STEP 6x2





STEP 7





①*4 ④*4

STEP 8





①*6 ④*6

STEP 9



③*4




STEP 10





②*4

⑤*4

STEP 11






STEP 12x2



①*2




④*2

STEP 13 x2





③*6

STEP 14 x2



③*4




STEP 15 x2






②*4

⑤*4

STEP 16 x2






STEP 17






③*4

STEP 18



③*8




STEP 19





②*4

⑤*4

STEP 20




STEP 21





③*4

STEP 22



③*12



STEP 23






②*4

⑤*4

STEP 24






STEP 25





③*4

STEP 26



③*12



STEP 27




②*4

⑤*4

STEP 28



STEP 29



STEP 30

