














An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a power drill should not be used.	A warning triangle icon with an exclamation mark inside.	A clock icon representing a time limit.
<p>20'</p>		
An icon showing a rectangular block on a mat with a diagonal line through it, and a block with a nail being driven into it, indicating that nails should not be used.	A warning triangle icon with an exclamation mark inside.	An icon of a person, representing the number of people required for assembly.
<p>1</p>		



1



2





3

H



x 2



4

I



x 1

