



GA3016




COMPONENTS




COMPONENTS

5




2PCS

6




1PC

7



1PC


8



1PC







COMPONENTS

9




1PC

COMPONENTS


<p>A</p>  <p>M6*55mm 8+1PCS</p>	<p>B</p>  <p>M3.5*25mm 2+1PCS</p>
<p>C</p>  <p>M3.0*18mm 8+1PCS</p>	<p>D</p>  <p>M3.0*14mm 12+1PCS</p>
<p>L</p>  <p>1PC</p>	<p>R</p>  <p>1PC</p>

Assembly Steps

1




2





Assembly Steps

3




4







D 12PCS


Assembly Steps


5



-  **C 8PCS**
-  **L 1PC**
-  **R 1PC**

6



-  **B 2PCS**



CONGRATULATIONS
YOU ARE DONE!