







Linn



1

2

3



1	1x
2	1x
3	1x

A	M6X20	B	M6X12	C	Ø18xØ6x1.5	D	4MM	E	M4x25	F	
	4x		4x		4x		1x		4x		2x

I.

1

E

M4x25

4x

F

2x

100%

2

B

M6x12

4x

D

4MM

1x

75%

3

A

M6X20

4x

C

Ø18xØ6x1.5

4x

D

4MM

1x

75%

4

D

4MM

1x

100%