


















ASSEMBLY INSTRUCTION



2

 (A) 4x	 (B) 4x
 (C) 4x	 (F) 4x
 (G) 4x	 (I) 4x
 (J) 4x	 (L) 4x
 (M) 4x	 (N) 12x
 (O) 8x	 (P) 8x
 (Q) 4x	 (R) 4x
 (U1) 8x	 (U2) 8x



M6*15

X1 128x




M6*40

X2 16x




M6*30


X3 16x




X4 12x




1 4x



2 4x




4 4x



5 4x



6 4x




7 8x




8 4x




10 4x



12 4x




13 1x



14 1x



15 4x



16 4x



18 8x



20 144x



21 5x




S4

1x

REQUIRED TOOLS



<1>



A 4x



8 4x




M6*15






X1 8x





20 8x




<2>

- **B** 4x
- **C** 4x
- **N** 8x
- 
M6*15
X1 40x
- **20** 40x





N 4x



10 4x




M6*15

X1 32x




20 32x

<3>



6



12 4x





X1 8x



20 8x

<4>



P 8x




X3 16x




20 16x



<5>







7



<6>




<7>



8



M 4x



6 4x



13 1x




X1 12x
M6*15



20 12x

<8>




X1 12x
M6*15



20 12x

<9>



9



L 4x





M6*15

X1 8x



20 8x

<10>




14 1x













21 1x


<11>





10

<12>

-  **1** 4x
-  **2** 4x
-  **4** 4x
-  **5** 4x
-  **F** 4x
-  **G** 4x
-  **I** 4x
-  **J** 4x
-  **Q** 4x
-  **R** 4x
- 11**



-  **M6*15**
- X1** 8x
-  **20** 8x

<13>



15 4x




16 4x






18 8x






21 4x




X4 12x




21
























X4



















12



10mm
25/64"

Carton-1/3	No	Reference Picture	Part	Qty
	1		A	4
	2		L	4
	3		M	4
	4		N	12
	5		8	4
	6		10	4
	7		6	4
Carton-2/3	No	Reference Picture	Part	Qty
	1		B	4
	2		C	4
	3		F	4
	4		G	4
	5		I	4
	6		J	4
	7		O	8
	8		P	8
	9		Q	4
	10		R	4
	11		U1	8
	12		U2	8
13	13	 M6*15	X1	128
	14	 M6*40	X2	16

Carton-2/3	No	Reference Picture	Part	Qty
	15	 M6*30	X3	16
	16		X4	12
	17		7	8
	18		12	4
	19		13	1
	20		14	1
	21		15	4
	22		16	4
	23		18	8
	24		20	144
	25		21	5
	26	 S4		1

Carton-3/3	No	Reference Picture	Part	Qty
	1		1	4
	2		2	4
	3		4	4
	4		5	4